

Standard Procedures

- Si : 400% , 300s for S/D activation
(P/As/BF₂ , 10~15keV , 1~2E15cm⁻²)
- Ge : 275% , 100s for S/D activation
(P/As/BF₂ , 10~15keV , 1E15cm⁻²)